



1/10  
FIG. 1




2/10

FIG. 2




3/10  
FIG. 3




4/10

FIG. 4




5/10

FIG. 5




6/10

FIG. 6




7/10

FIG. 7




8/10

FIG. 8





9/10  
FIG. 9



10/10

## Reference numerals in the drawings

- 11 refrigerator
- 12 door
- 13 front face
- 14 inner face
- 15 heat insulator
- 16 water feeder
- 17 water storage tank
- 18 water feeding tube
- 18b water feeder outlet
- 18d water feeder outlet guide
- 19 canopy
- 20 sliding rod
- 21 spring
- 22 rubber lid
- 23 pin
- 24 water feeding lever
- 24d dual ribs
- 28 guide member
- 25 tank cover
- 26 tank cap

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**